Work Order ID 60047 Wednesday, June 23, 2010 1:12:27 PM											Page 1
Item ID: Revision ID:	D4035-043		AAA	Accept				s s	etup Star		
Item Name:	Lid Rib Assem	nbly, Aft (350 Basket)							Sto	р	
Start Date: Required Date: Reference:	6/23/2010 6/30/2010	Start Qty: 2.00 Req'd Qty: 2.00	1 1 1 1 1 1 1 1 1 1		Cust Item II Customer:) :			1		
Approvals:	Process Pla	n:	Date 10-6-2		, Da			F	tun Star Sto	1 18811181 8	
	QC:		Date:	_ SPC (Y/N):	Da	te:					
Sequence ID/ Work Center ID)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	. Revi	ision Nbr			-						
D4035	A									20	
100 Large Fab		Weld per dwg A/R S. Memo	S. rod Batch: 111675	0.00			- 1 - 1	(3)	Cpl	10.00	6.09
Large Fab		1- Cut D4 2- Drill ho 3- remove	035-3 as per dwg D4035 bles using DT9563 and cham identification marks and de ushing in rib and grind weld	nfer holes as per dwg D403 burr	SA() 10-	06-2	8_			

0.00

0.00

(D) 10.01.01

QC9- Inspect visual per QSI004- Fusion Welds

Memo

110

Quality Control

11110			10.	ODI ODDED OUANG	\					
W/O:			W	ORK ORDER CHANC	iES					
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										,
		·								
					1					•
									·	
						·	ľ			
									•	
Part No	•	PAR #:	Fault Cat	egory:	NCI	R: Yes	No DQA :		Date:	
	R	esolution:	Disposition: QA: N/C Closed:							
NCR:	:	·	WORK ORI	DER NON-CONFORM	ANCE	(NCR)			,
DATE	OTED	Description of NC			tion B		Verifica	ion	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	С	Chief Eng	QC Inspector
									į	* ,
								-		
								<u> </u>		· · ·
						į		1		
						1				
										-

Work Order ID 60047

Wednesday, June 23, 2010 1:12:27 PM



Page 2

Item ID:

D4035-043

Accept

Setup Start



Revision ID:

Item Name:

Required Date: 6/30/2010

Lid Rib Assembly, Aft (350 Basket)

Start Date:

6/23/2010

QC:

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID: Customer:

Reference:

Approvals:

Process Plan:

Date: _____

Date:_____

Tooling:

SPC (Y/N):

Run

Start

Stop

Stop



Sequence ID/ Work Center ID

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

Memo

Memo

Set Up/

Run Hours

Tool ID

Date:

Date:

Tool # Plan Code

Accept Qty Qty

Reject Reject Number

Insp. Stamp

130

Packaging Packaging

Identify as per dwg & Stock Location:

0.00

PD 10.07.01

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/07/01957 MF 10-4-0'

W/O:		WORK ORDER CHANGES								•
DATE	STEP	PROC	EDURE CH			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						a'			·	
							·			
-										
Part No		PAR #:	_ Fault Ca	tegory:	_ NCF	R: Yes	No DQA :		Date:	
	R	esolution:	Disposition: (N/C CI	osed:		Date: _	
NCR:			ORK OR	DER NON-CONFORMA	NCE	(NCR)			
DATE	STEP	Description of NC		Corrective Action Section	on B	Ciam 0	Verifica		Approval	Approval
DAIL	OIL.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section	ıC _	Chief Eng	QC Inspector
	,		ļ							
								İ		
·							į			
								1		
				,						
				·						
							ļ			:
,							-			

Picklist Print

Wednesday, June 23, 2010 1:12:32 PM

Work Order ID: 60047

Parent Item:

D4035-043

Parent Item Name: Lid Rib Assembly, Aft (350 Basket)



Start Date: 6/23/2010

Required Date: 6/30/2010

Page 1

Start Qty: 2.00

Required Qty: 2.00

Comments:

IPP revA: new issue DD 09.11.25 verified by:EC

per dwg revA 10.03.15 verified by:EC


IPP Rev:B as

	per a g re 1 10.0.	one vermed by .12	C										
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D4021-9 Bushing		Manufactured	No			100	Each	24.0000	2	4	Eps	10	060
				Location	1	Loc	Oty	Loc Code					
•				WA			24		·		_		
					56094		2					1	
					58701		6				_	i	
					59838	•	16		7	4/	-	- 1	
M304TS0.750W.049		Purchased	No			100	f	441.5314	1.75	3.68421	- 1	j	•


304 SQ Tube .75x.75x.049W

Location	1	Loc Qty	Loc Code	
MAT		141.5313919		•
	113763	0		
	114323	28.3020789		
	114677	14.34201		
	114835	98.887303	•	
MAT017	•	3.68448E-05		
	114298	3.6845E-05		
WA		300		
	114992	300		


W/O:			WORK ORDER CHANGES							
DATE	STEP	PROC	EDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
T-10. 1-										
Part No	•	PAR #:	PAR #: Fault Category: NCR: Yes No DQA:							
	R	esolution:	_ Disposit	ion:	QA:	N/C Clos	sed:		Date:	
NCR:		W	ORK OR	DER NON-CONFORM	ANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng	tion B	Sign & Date	Verifica Section		Approval Chief Eng	Approval QC Inspector
			Office Eng	Office Eng		Date			`	
					•					
										,
,					:					
			5 1							
							·		-	
							-			




W/O:			WORK ORDER CHANGES							
DATE	STEP	PROC	EDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									,	
						,		· -		
								h.		
Part No	:	PAR #:	_ Fault Cate	gory:	NCR: Yes	No DQA:		_ Date: _		
	R	esolution:	_ Dispositio	n:	_ QA: N/C C	closed:		Date: _		
NCR:			ORK ORD	ER NON-CONFORMA	ANCE (NC	R)				
DATE	CTED	Description of NC		Corrective Action Section		Verifica	ion	Approval	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Section		Chief Eng	QC Inspector	
					-	1	· .			
								·		
`		·						,		
	· ·	. ,					ļ			
									·	
		,	1		1	i		1	ı	




				•							
W/O:			V	VORK ORDER CHANG	SES						
DATE	STEP	PROC	CEDURE CH	IANGE	Ву	Dat	e	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
										·	
		·									
Part No	art No: PAR #:			tegory:	_ NCR: Ye	s No	DQA:				
Resolution:			_ Disposit	tion:	QA: N/C	Closed			Date: _		
NCR:		W	ORK OR	DER NON-CONFORM	ANCE (N	CR)					
DATE	STEP	Description of NC			tion B	V	Verification Section C	ion	Approval	Approval	
	SILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da		Section	C	Chief Eng	QC Inspector	
v.	·							, .			
· ·		-									
	-										
: 										i i	



W/O:		WORK ORDER CHANGES						n de la companya de l		
DATE	STEP	PRO	OCEDURE CHAI	NGE	В	у	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,										
Part No):·	PAR #:	Fault Cate	jory:	NCR:	Yes N	o DQA:		_ Date: _	
	R	esolution:	Disposition	n:	QA: N	C Clos	sed:		Date:	· · · · · · · · · · · · · · · · · · ·
NCR:			WORK ORDI	R NON-CONFORT	MANCE (I	VCR)				
DATE	STEP	Description of NC			ection B		Verifica	tion	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	n S	ign & Date	Section	С	Chief Eng	QC Inspector
								, -		
11 11										
									1	



W/O:	WORK ORDER CHANGES											
DATE	STEP	PROC	EDURE CH	IANGE	Ву	Date	ty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
								•	· .			
Part No	:	PAR #:	_ Fault Ca	tegory:	NCR: Yes	No DQA:		Date: _	· · · · · ·			
	Resolution:		_ Disposition: QA: N/C Closed:					Date:				
			ORK OR	DER NON-CONFORMA	NCE (NCR)						
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	Sign &	Verificat Section		Approval Chief Eng	Approval QC Inspector			
									,			
	;											



W/O:			WORK ORDER CHANGES									
DATE	STEP	PROC	EDURE CH	IANGE	Ву	,	Date	ty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						-						
Part No):	PAR #:	_ Fault Ca	tegory:	_ NCR: Y	es N	lo DQA:		_ Date: _			
			Disposition: QA: N						Date:			
NCR:		W	ORK OR	DER NON-CONFORMA	NCE (N	CR)						
DATE	STEP	Description of NC Section A	Initial	on B	Verifica Section		Approval Chief Eng	Approval QC Inspector				
			Chief Eng	Chief Eng		ate						
<u>.</u>												
								-				
		,										
					,			l				
								lacksquare				
			1					1				